

# TECHNICAL NEWS 208



## Notice Information

Ref	14565
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Aftersales Manager, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

## TOL NOTICE (US&CA) – April 21, 2020

TOL Ref. # 14565-SVC

### TECHNICAL NEWS 208

Technical News 208 is now available for download on the Triumph Technical News library located at **Triumph Online > Service/Technical > Technical News** or you can consult the attached **Technical News 208** PDF. Please ensure your workshops and all relevant staff are aware of the contents and any absent staff are informed upon their return. Please also update your workshop service manuals, procedures and have a printed copy available where appropriate.

Technical News 208		
Item	Subject	Model Affected
208.1	Triumph Diagnostic Tool 2020-04.3 Update	All models with TFT instruments
208.2	Keyless Ignition - 'Key Fob Out of Range' and 'Key Fob Battery Low' Instrument Messages	Rocket 3 GT, Rocket 3 R, Rocket 3 TFC, Scrambler 1200 XC, Scrambler 1200 XE, Speed Triple RS, Tiger 1200 XRX, Tiger 1200 XRX-LRH, Tiger 1200 XRT, Tiger 1200 XCX, Tiger 1200 XCA

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.