

# SERVICE BULLETIN 572: SEAT FINISHER PANEL



## Notice Information

Ref	14588
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Aftersales Manager, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

## TOL NOTICE (US&CA) – April 27, 2020

TOL Ref. # 14588-SVC

### SERVICE BULLETIN 572: Seat Finisher Panel

Triumph has released **Service Bulletin 572**. Internal investigations have identified the need to fit seat trim to the seat finishers to improve the cosmetic appearance on the above models. Dealers are requested to fit the seat trim to the seat finishers as described in the procedure outlined in the [Service Bulletin 572 PDF](#).

SB 572: Seat Finisher Panel			
Bulletin #	Models Affected	VIN Range	Markets
572	Rocket 3 R Rocket 3 GT Rocket 3 TFC	From 978634 to AA4338	All

Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next visit to the dealership.

Consult **Triumph Online (TOL) / Service Bulletin Page** (Bulletin # 572) or the attached [Service Bulletin 572 PDF](#) for additional information including Fitting, Warranty Claim and Part Ordering instructions. Please also ensure that all relevant staff are up to date on these service instructions.

**Reminder:** Use the “**VIN Enquiry**” function within TOL (found under the **Service / Technical** drop down menu) to search for any outstanding bulletins or recalls whenever a new motorcycle arrives or a Triumph owner visits your dealership.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.