



<b>DTC (Code)</b> P1059-98 <b>Codigo:</b>	<b>Bulletin:</b> RD18-002 <b>Date Fecha:</b> February 11, 2019
<b>Description:</b> Gearbox Oil Temperature Sensor (SETeGO) - Component or system over temperature	
<b>Application:</b> US13 – US20 Emissions	

**General Information**

These repair instructions are intended to address the following fault(s):

DTC	Description	Possible Cause	Possible (Observable) Symptoms
P1059 – 98	Gearbox Oil Temperature Sensor (SETeGO) - Component or system over temperature	<ul style="list-style-type: none"> <li>• Poor cooling</li> <li>• Lubrication and Oil System</li> <li>• Low oil level</li> <li>• Oil leakage</li> </ul>	Transmission high oil temperature warning

**Required Parts**

Part Number	Description	Quantity
N/A	N/A	N/A

**Repair Instructions**

Visual Inspection & Tech Tool Diagnostics

1. Check engine coolant level. If the fluids are not at an acceptable level please check and diagnose for fluid leakage.
2. Check transmission oil level. If the fluids are not at an acceptable level please check and diagnose for fluid leakage.
3. Please connect to Tech Tool for further fault tracing and diagnostics.

**Additional Resources**

These repairs are the most likely fix for the identified fault, if this does not fix the issue, Tech Tool will need to be used for more detailed diagnostics. If filin

<b>Labor Code</b>	
N/A	N/A
<b>Causal Part</b>	N/A