9004238 03/11/2020 MY20 DT

GPOP - Issue Review System

Part Number: 68316081A\$, 68316080A\$, 68316087A\$, 68316086A\$

Part Description: Headlamp

Issue After performing the headlamp condensation clearing service procedure, If the **Description:** headlamp is being replaced for a Moisture/Condensation issue, please e-mail and call *FCA Redacted Content* and send pictures of the Moisture/Condensation issue to *FCA Redacted Content* and *FCA Redacted Content* as part of the repair.

If no response in 15 minutes, proceed with repair.

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.