

STAR ONLINE PUBLICATION

Case Number: S2024000002

Symptom/Vehicle Issue: WiTECH HVAC Actuator Calibration Test Reserved Tab.

Discussion: The WiTECH HVAC actuator calibration routine is showing a “Reserved” tab on the screen. This tab is erroneous and has no function for the vehicle. The tab will be removed in the next WiTECH Release.

2020 JEEP GLADIATOR 3.6L V6 24V VVT ENGINE UPG I W/ESS
1C6HJTAG8LL125948

12.80 Volts

Actuator Calibration Test

Actuator Calibration Test Complete

Name	Value
Actuator 0 (Front Mode 1 Panel) Calibration Passed Flag	True
Reserved	False
Actuator 2 (Right Temp) Calibration Passed Flag	True
Actuator 3 (Recirc) Calibration Passed Flag	True
Actuator 4 (Left Temp) Calibration Passed Flag	True

Close

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found