

GPOP - Issue Review System

Part Number: 68282010A\$

Part Description: Gasket, Timing Gear Housing

Issue Description: For 2019, and 2020 Model Year Only. If you are replacing the timing housing gasket due to an oil leak, please take detailed pictures of the leak, and submit them to the Star Center. Once submitted, continue with the repair.

During the repair, check the breakaway torque of the gear housing retaining bolts. If any are found to be loose, note the location of the loose bolt(s) in the Star case.

~ _____ ~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.