## **GPOP - Issue Review System**

Part Number: 68347098A\$

Part Description: MODULE, Anti-Lock Brake System

Issue If ordering ECU PN 68347098AB or later to repair a C0020-01 ABS PUMP MOTOR Description: CONTROL - GENERAL ELECTRICAL FAILURE, The HCU Hydraulic Control Unit

can be replaced alone for this DTC.

For any other DTC's follow published diagnostics.

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.