

## **GPOP - Issue Review System**

**Part Number:** 68413389A\$, 68277136A\$

**Part Description:** MODULE, Trailer Tow (Integrated Trailer Brake Module - ITBM)

**Issue Description:** For concern of error message "Park Assist System Disabled" displayed on the Cluster with DTC U0137 stored or active, please review the communication path between the ITBM and PTS (Parktronics – Park Assist System).

Follow U0137 and Communication Diagnostic Procedure to rule out potential improper connector installation, damage harness / connector, water intrusion, or TPO issues. If the DTC U0137 is stored, please do 5 ignition cycles from bus sleep mode and verify if the DTC becomes active. If the DCT U0137 is active, please create and email a copy of the Scan Report to:

*FCA Redacted Content*

We will review the scan report and let you know next step as soon as we can. Please contact *FCA Redacted Content* for any questions.

If no response in 15 minutes, proceed with repair.

~\_\_\_\_~  
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

---

