

GPOP - Issue Review System

Part Number: 68249191A\$, 68217322A\$, 68399021A\$

Part Description: COOLER, Transmission Oil

Issue Description: Work procedure to address fluid leak issue with the transmission oil cooler on the MP (Part # 68249191A\$), KL (Part # 68399021A\$) and RU (Part # 68217322A\$) needs to be followed.

Service Instructions for the Condition of a TOC fluid leak:

- 1) Mark the leakage area if visible to assist in diagnosis and determination of the area where the leak has occurred.
- 2) If fluid leak was caused by damage or leakage at the transmission oil cooler:
 - Replace transmission oil cooler
 - Test drive and verify no additional fluid leaks
- 3) If fluid leak was caused by leak at quick connect fittings:
 - Replace transmission oil cooler lines
 - Test drive and verify no additional fluid leaks

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
