

## STAR ONLINE PUBLICATION

**Case Number:** S1808000152


**Release Date:** 04/30/2020

**Symptom/Vehicle Issue:** CEL (Check Engine Lamp) Illuminates, Recent PCM Replace Or Flash Update Performed, DTC P057B Brake Pedal Position Sensor Circuit Performance

**NOTE: THE PCM - BRAKE PEDAL LEARN MUST BE PERFORMED ANY TIME A PCM IS REPLACED OR UPDATED.**

**Discussion:** If the vehicle sets a P057B or a P1572 DTC, and there was a recent service procedure that may have involved replacing and/or updating the PCM, a required brake pedal learn procedure should be performed, no added parts required upon completion and clearing of DTC(s).

If the DTC's are setting after completion of the above and/or the a PCM replace and/or update has not been performed and the codes are setting, continue with the normal DTC diagnostics in Service Library to complete.



**OTE: If the PCM does not have the above listed “Brake Pedal Learn” option available under the MISC Functions folder, then this SOL publication does not apply, follow the normal diagnostics to resolve.**

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**