



Technical Journal

TITLE:

Trunk lid, water intrusion

REF NO: TJ 35409.4.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2020-03-12	STATUS DATE: 2020-04-02
FUNC GROUP: 8320	FUNC DESC: Boot lid, tailgate with hinge and support	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
246							2018-2099		0000001-0999999	201717-209952

CSC Customer Symptom Codes

Code	Description
R5	Tailgate/trunk lid/Water leakage

VST Operation Number

VST Operation Number	Description
98744-2	Luggage Compartment Lid Moulding

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

If the vehicle shows sign of water intrusion into the trunk, through tail gate sealing in the lower area near rear bumper, see information and follow instruction described under “Service”.

**SERVICE:**

If car shows symptom as described in description, follow service solution described in VIDA.

*Information=> Bulletins => Product Fix Bulletins => 8 Body and interior => 84 Exterior trim, glass, weatherstrips => 845 Luggage Compartment Lid Moulding

Part number sealing 32282741.

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data: VST OP number: 98744-2

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8320.