

WLC8 Workshop Campaign - Replacing tank leakage diagnosis module

Version 2

WLC8 Workshop campaign - Replacing tank leakage diagnosis module

Update 5/29/20

An additional parts allocation of 30% UIO is underway at PDCs and expected to arrive to dealers no later than 6/9. If you have not received additional allocation as expected by 6/9, please contact your facing PDC to inquire about the allocation, as needed.

Overview

Under certain regional environmental conditions, e.g. dust and humidity, there is a possibility that particles of dirt can get into the tank leakage diagnosis module.

This can cause an over-sensitive tank leakage diagnosis and the Check Engine light may be activated.

To prevent this, the tank leakage diagnosis module and the air filter for the carbon canister must be replaced.

Please arrange for this measure to be carried out on the affected vehicles the next time the vehicles come into the workshop.

Model type	911 Carrera (991)
Model year	2012 to 2016
Number	26,217

Parts required

Part No.	Designation	Quantity/vehicle	Parts return*
00004321110	Pressure switch	1	No
00004321007	Filter	1	No

* The parts must be stored until such a time as the **related warranty or campaign claim has been credited** in WWS. If a **barcode is generated** with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the genuine remanufactured parts process or be scrapped.

Ordering required parts

An initial auto-allocation of the required parts has been completed and parts shipments are underway. Please do not order additional parts for this campaign.

Warranty processing

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

Scope 1:

Damage code

WLC8 66 000

Repair code	2
Working time	42 TU

Further information

Work instruction	TI No. 45/20, Group 2, Service, WLC8
Vehicle list and allocation	See PCSS or attached VIN list for reference
Technical Information*	See PCSS or attached PDF for reference

* Please find enclosed the Technical Information in the form of a PDF file. Please bear in mind that this is provided for your information only. The version published in PCSS is the definitive version.

For further information, please contact:

Ryan Cooney

Regulatory Affairs

ryan.cooney@porsche.us

[991 2 45-29 WLC8 Replacing Tank Leakage
Diagnosis Module \(Workshop Campaign\).pdf](#)

299.7 KB

(340 views)

[WLC8 VIN List.xlsx](#)

515.2 KB

(40 views)

Created by [Ryan Cooney](#) on May 5, 2020 10:43 PM. Last modified by [Ryan Cooney](#) on May 29, 2020 9:19 PM.

Categories: Workshop Campaigns, 911 Carrera

Tags : [workshop](#), [991 carrera](#), [year_l](#), [wlc8](#)

1890 Views

[Report Abuse](#)

Content and Topics

Personal

Manage

Create

Your Groups >

Edit Profile >

Admin Console >

Discussion >

Your Content >

Change Password >

PPN Administration >

Files >

Your Places >

Document >

Collaboration >

Document

Blog Post >

Poll >

Event >

Photo Album >

Idea >

Space >

Group >

© 2020 Dr. Ing. h.c. F. Porsche AG. [Legal notice.](#) [Copyright.](#) [Terms of use.](#) [Privacy Policy.](#) [Cookie Policy.](#) **009**