

WKJ3 Workshop campaign - Replacing tank leakage diagnosis module

Version 2

WKJ3 Workshop campaign - Replacing tank leakage diagnosis module

Update 5/29/20

An additional parts allocation of 30% UIO is underway at PDCs and expected to arrive to dealers no later than 6/9. If you have not received additional allocation as expected by 6/9, please contact your facing PDC to inquire about the allocation, as needed.

Overview

Under certain regional environmental conditions, e.g. dust and humidity, there is a possibility that particles of dirt can get into the tank leakage diagnosis module.

This can cause an over-sensitive tank leakage diagnosis and the Check Engine light may be activated.

To prevent this, the tank leakage diagnosis module and the air filter for the carbon canister must be replaced. Please arrange for this measure to be carried out on the affected vehicles the next time the vehicles come into the workshop.

Model type	Boxster (981) and Cayman (981)
Model year	2013 to 2016
Number	17,975

Parts required

Part No.	Designation	Quantity/vehicle	Parts return*
00004321110	Pressure switch	1	No
00004321007	Filter	1	No

* The parts must be stored until such a time as the **related warranty or campaign claim has been credited** in WWS. If a **barcode is generated** with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the genuine remanufactured parts process or be scrapped.

Ordering required parts

An initial auto-allocation of parts for this campaign has been completed and shipment is under way. Please do not order additional parts for this campaign.

Warranty processing

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

Scope 1:

Damage code	WKJ3 66 000
-------------	-------------

Repair code	2
Working time	58 TU

Further information

Work instruction	TI No. 123/19, Group 2, Service, WKJ3
Vehicle list and allocation	See PCSS or attached VIN list for reference
Technical Information*	See PCSS or attached PDF for reference

* Please find enclosed the Technical Information in the form of a PDF file. Please bear in mind that this is provided for your information only. The version published in PCSS is the definitive version.

For further information, please contact:

Ryan Cooney

Regulatory Affairs

ryan.cooney@porsche.us

[981 2 123-19 WKJ3 Replacing Tank Leakage](#)

[Diagnosis Module \(Workshop Campaign\).pdf](#)

303.9 KB

(180 views)

[WKJ3 VIN List.xlsx](#)

358.2 KB

(45 views)

Created by [Ryan Cooney](#) on May 5, 2020 11:19 PM. Last modified by [Ryan Cooney](#) on May 29, 2020 9:15 PM.

Categories: Cayman, Workshop Campaigns, Boxster

Tags : [workshop](#), [981](#), [year k](#), [wkj3](#)

1526 Views

[Report Abuse](#)

Content and Topics	Personal	Manage	Create
Your Groups >	Edit Profile >	Admin Console >	Discussion >
Your Content >	Change Password >	PPN Administration>	Files >
Your Places >			Document >
			Collaboration >
			Document
			Blog Post >
			Poll >
			Event >
			Photo Album >
			Idea >
			Space >
			Group >

© 2020 Dr. Ing. h.c. F. Porsche AG. [Legal notice.](#) [Copyright.](#) [Terms of use.](#) [Privacy Policy.](#) [Cookie Policy.](#) [009](#)