

5/26/2020  
CAL FTL 54-008

## **Subject: ABS ECU Software Update**

**Models Affected: On Freightliner and Western Star vehicles with  
72.5" axle spread.**

Our records indicate that you are the owner of certain vehicles, and DTNA has decided to share the following documentation with you.

We hope you find this information helpful.

The Enhanced Stability Control (ESC) function within the ABS module that applies to the vehicles in your possession needs to be updated for the axle spread values. The ESC with the current values functions as it should, but should be updated to ensure proper calibration in the future. To correct this discrepancy, please visit an authorized Freightliner dealership to have the ABS controller updated to the latest software version.