

2020-05-28

[illegible]

Table 2. Rate for Out of Warranty Repairs

REPAIR	COST
Initial inspection and diagnosis	\$60.00
Replace air bladders (seat and pillion)	\$95.00
Replace compressor/wire harness	\$145.00
Replace vinyl seat and pillion cover	\$155.00
Replace leather seat and pillion cover	\$215.00
Switches (grouping of two or three)	\$50.00
Base repairs	Not serviced
Foam cushions (only serviced along with cover)	\$40.00
Other items quoted after analysis*	TBD
*See note which follows.	

NOTE

**The design of the compressor and reservoir system is different between the -97E and -09 versions. All -97 versions can be repaired using the updated (-09) system. In some instances this may not be financially viable.*

3. Dealership must send seat back to:
Milsco Manufacturing Company
Attn: Road Zeppelin Service Department
650 Bannerman Avenue
Redgranite WI 54970 USA

NOTE

For emergency contact by the dealership only: info@milsco.com, or 414-354-0500 Ext 3997; or directly at 414-410-3997

4. The seat will be repaired within ten (10) working days of receipt at Milsco.
5. The seat will then be shipped back to the dealership. The dealership will be billed for repairs and returned shipping costs directly by Milsco via invoice returned with the seat. Shipping costs from the dealership to Milsco are to be paid by the dealership. Dealer is to make checks payable to Milsco within 30 days.
6. Warranty for repaired items is 90 days from repair.

Canada Market

Canadian dealers: costs are in U.S. Dollars. Also, there may be brokerage duties costs in addition to the shipping costs incurred.