



Preliminary Information

PIT5744 Disabling Side Blind Zone Alert and/or Park Assist Systems When Removing Pickup Box and/or Bumper

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	All	All
Chevrolet	Silverado 1500	2020	All	All	All	All
GMC	Sierra 1500 (New Model)	2019	All	All	All	All
GMC	Sierra 1500	2020	All	All	All	All

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Involved Region or Country	North America
Additional Options (RPO)	UD5, UD7, or UKC
Condition	A customer may request the pickup box and rear bumper be removed to install an aftermarket bed or body. If the vehicle is equipped with Side Blind Zone Alert (UKC) or Park Assist (UD5/UD7) there will be "Service" messages displayed on the DIC due to missing modules and sensors after the box and rear bumper are removed.
Cause	Information not readily available in Service Information (SI.)

Correction:

Reference the latest version of GM Upfitter Integration Bulletin 168. The information can be found at <http://www.gmupfitter.com/> under the "Technical Bulletin" Tab and then "Show all bulletins."

Version History

Version	1
Modified	05/26/2020 - Created onper BQM Kevin Minor request.

