

STAR ONLINE PUBLICATION

Case Number: S2008000033

Release Date: 05/19/2020

Symptom/Vehicle Issue: MIL Lamp On, DTC P0325 - Knock Sensor 1 Circuit

Customer complaint/Technician observation: Customer complains that MIL lamp Malfunction Indicator Light (MIL) is on. Technician observed DTC P0325 knock sensor 1 circuit as stored or active.

Discussion: Inspect the engine harness routing at the rear of the engine as shown Fig 1, 2. Review for any signs of chaffing damage, repair and isolate the harness concern as needed, no parts required.




Fig 1

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

STAR ONLINE PUBLICATION




Fig 2

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found