

Service Bulletin

Bulletin No.: 20-NA-101

Date: June, 2020

TECHNICAL

Subject: Premature and/or Uneven Brake Pad Wear Heavy Duty ONLY

Brand:	Model:	Model Year:		Breakpoint:		Engino	Transmission:
		from	to	from	to	Engine:	Transmission.
Chevrolet	Silverado HD	2015	2018	-	-		
	Silverado 2500/3500	2019	2019				
GMC	Sierra HD	2015	2018				-
	Sierra 2500/3500	2019	2019				

Involved Region or Country	United States, Canada, Mexico, Middle East, Iraq, Israel, Palestine		
Condition	Some customers may comment on premature and/or uneven brake pad wear.		
Cause	This condition may be caused by friction material having different wear characteristics.		
Correction	Replace the affected pads with one of the new P/N's listed below.		

Service Procedure

Refer to Front Disc Brake Pads Replacement and Rear Disc Brake Pads Replacement in SI.

Parts Information

Refer to the electronic parts catalog (EPC) for obtaining the correct P/N.

Causal Part	Description	Part Number	Qty
	PAD KIT, FRT DISC BRK (J96/J95)	22770745	
Х	PAD KIT, RR DISC BRK (J95)	20829195	1
	PAD KIT, RR DISC BRK (J96)	20828610	

Warranty Information

This condition, if applicable, will surface around 3000-17,000 miles (4,828 — 27,359 km) with extremely biased wear on only one of the 2 pads. Uneven or any lining wear greater than 17,000 miles (27,359 km) would not be this condition and should be considered general wear. For vehicles repaired under warranty, please use the appropriate warranty labor operation based on the original cause in addition to well documented straight time, if necessary.

Version	2	
Modified	Released May 20, 2020	
	Revised May 29, 2020 — Updated Warranty Information.	

