

SUBJECT:			No:	SR-20-002	
SEAT BELT -	DATE:	May 2020			
			MODE	SEE BELOW	
CIRCULATE TO:	[X] GENERAL MANAGER	[X] PARTS MANAGER	[X] PARTS MANAGER [X		
[X] SERVICE ADVISOR	[X] SERVICE MANAGER	[X] WARRANTY PROCESS	) R	[X] SALES MANAGER	

#### PURPOSE

This Safety Recall Bulletin provides instructions for inspecting the 2<sup>nd</sup>-row RH-side (passenger side) seat belt shoulder anchor. If necessary, the seat belt will be replaced.

#### BACKGROUND

Due to inappropriate manufacturing process at the supplier, the guide piece (which is a component part of the second row seat belts' anchorage) for the left side seat belt was mistakenly assembled with the right side seat belt, causing seat belt restraint efficiency for vehicle occupants to decrease in a vehicle collision, increasing the risk of injury.

### AFFECTED VEHICLES

Certain 2020 Outlander vehicles Certain 2020 Outlander PHEV vehicles

### **IMPORTANT**

Affected new or used inventory vehicles must be repaired before the vehicle is sold/delivered. Dealers must check their inventory vehicles' VINs on the Warranty Superscreen to verify whether the vehicle is involved in this recall campaign. It is a violation of Federal law for a dealer to sell/deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied.

### **CUSTOMER NOTIFICATION**

A letter will be sent to all owners of affected vehicles telling them to contact their local Authorized Mitsubishi Motors dealer to have the 2<sup>nd</sup>-row RH-side shoulder anchor inspected. If the anchor guide is found to be incorrect, the seat belt will be replaced.

Copyright 2020, Mitsubishi Motors North America, Inc.

Continued

Page 1 of 4

The information contained in this bulletin is subject to change. For the latest version of this document, go to the Mitsubishi Dealer Link, MEDIC, or the Mitsubishi Service Information website (*www.mitsubishitechinfo.com*). (4944)

Page 2 of 4 SR-20-002

# SEAT BELT ANCHOR INSPECTION PROCEDURE

1. Turn over the belt at shoulder anchor part of the rear right side seat belt.



#### **REPLACEMENT PROCEDURE**

1. The replacement procedure will require the removal of the seat and various trim components. Please refer to the applicable service manual for removal and installation instructions.

## **PARTS INFORMATION**

Use the genuine Mitsubishi Part listed below:

Description	Part Number	
REAR SEAT BELT OUTER RH	7000D540XA	

### WARRANTY INFORMATION

There are only 2 repair scenarios for this campaign.

## WARRANTY / RECALL CAMPAIGN CLAIM INFORMATION

Enter all claims as claim type 'C' - Recall/Campaign Claims.

Please follow the campaign instructions when entering each claim. See the claim example provided below.

Certain 2020 MY Outlander and 2020 MY Outlander PHEV models.

#### **Recall Claim Header Section:**

	ER			e Warranty anty Claim			-A		Help
Claim	n Entry	Vehicle Inform	Enter in the firs paign number:		ers of the	cam-	face	PQR/VQR	
Campaig	n Inforn	nation							<b>1</b>
Campaign Operation No	C2002R			Ente	er As	F	тср		
NO Miles/Km VIN			Check the Open certain of a vehi involved.						
Service Technicia	n J.	Emp I	No	Service Ac	dvisor		Emp	No	
Spec Valu	e *				Dup	licate Re	tall *		
Dealer:	99320	Ref No:				VIN:			
Claim No:		Adj:	Claim	Status:	Incomp	plete Mode	and Year:		
			Save & Continu	e Ma	lin Menu	]			

After entering the required customer data, vehicle information, selecting the applicable repair campaign and scenario performed (please note there are only 2 possible repair scenarios for this campaign), and then clicking the "Save and Continue" button, the system will automatically fill-in several fields.

Page 4 of 4 SR-20-002

# **LABOUR OPERATIONS:**

There are only 2 possible repair scenarios for this campaign.

Involved Models		Campaign Op# Labour Time		Repair Description	
1	Outlander / Outlander PHEV	C2002R01	0.3	Inspected Seat Belt-Passed -Replacement Not Needed	
2	Outlander	C2002R02	0.6	Inspection Failed – Replace Seat Belt	
	Outlander PHEV	C2002R03	0.8	Inspection Failed – Replace Seat Belt	

# **RENTAL CARS:**

If there is a need to provide the owner with a rental vehicle, contact the Canadian Warranty Department as per Warranty Bulletin WB2012-001