

Subject

A25A Engines - MIL ON and/or Coolant Leak from Water Pump

Market

USA

Service Category

Vehicle Interior

Section

Meter/Gauge/Display

Applicability

2020 Applicable Models with A25A Engine

APPLICABLE VEHICLES

2020	Avalon HV	2020	Highlander HV
2020	RAV4	2020	Camry
2020	RAV4 HV	2020	Camry HV

CONDITION

Some 2020 model year models equipped with A25A-FKS or A25A-FXS engine may exhibit a MIL ON with one or more of the following DTCs (P26CB71, P26CA14, and P26CA31) and/or coolant leak from electric water pump body or electrical connector.

RECOMMENDATIONS

This issue is currently under investigation.

Please contact Technical Assistance (TAS) for further direction before proceeding with work on the vehicle.

If it is a weekend or holiday, continue with diagnosis or repair. Please save all parts and/or relevant details and contact TAS on the next available work day.

LINK REFERENCES

This Tech Tip does not contain any link references