



Condition

ATTENTION:

**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Golf, GTI, Golf Sportwagon, Alltrack	2015	All	All	All	All

Revision Table

Instance Number	Published Date	Version Number	Reason For Update
2059903/1	6/19/20	91-20-08TT	Original publication.

Technical Background

Customer concern indicating that the radio display flickers while radio is ON.

Service

Replace the **-J794-** Information Electronics Control Module 1, 5F module. After performing the replacement test plan, perform the control module software configuration test plan and the function clearing system FES test plan, selection #2.



Figure 1: Example of radio flickering



Additional Information

© 2020 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.