

[Next Unread Message](#)**View Message**

<b>Sent on</b>	06	15	2020	<b>Expires on</b>	06	29	2020
<b>From</b>	Parts and Service Division						
<b>Subject</b>	Request for Parts: 2014-2019 MDX & TLX Fuel Leak at Fuel Joint Pipe						

**PRIORITY/ACTION REQUIRED**

To: All Acura Service Managers/Consultants  
 From: Technical Research & Support Group  
 RE: Request for Parts: 2014-2019 MDX & TLX Fuel Leak at Fuel Joint Pipe

**This message is solely directed to Acura dealership personnel; please handle accordingly.  
 Print this iN message and provide a copy to the Shop Foreman and all Service Consultants.**

**Background**

American Honda Motor Co., Inc. (AHM) is investigating certain 2014-2019 MDXs & 2015-2019 TLX with a client complaint of a fuel leak at the fuel joint pipe. To better understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirement:

1. Must trace the fuel leak to the fuel joint pipe at the fuel pump or the rail connection.
2. No repair has been attempted for this issue.
3. No prior history of the fuel joint pipe replacement.

**Action Required**

If a vehicle matching the qualifiers above comes into your dealership, please e-mail Technical Research & Support (TRS) at [trs@ahm.honda.com](mailto:trs@ahm.honda.com). TRS will contact you to record certain vehicle information and provide you with further instructions.

Please be sure to include the following information in your e-mail.

E-mail Title:

1. Model Year (e.g. 2019)
2. Model Name (e.g. TLX)
3. Issue (e.g. Rear Brake Noise)
4. VIN

E-Mail Body:

1. Dealer Number
2. Your Name
3. Best Phone Number to be Reached
4. Current Mileage

Thank you.