



ROADSTER 2020-2 Repair Procedure Revision- Brake Light Switch Adjustment_000137793_SER61Y020S06_en

Product: **Roadster**

Bulletin type: **Service**

Bulletin no: **2020-2** (rbs2020-003 en NL)

Revision no:

Revision date:

Campaign no.:

Publication date: **June, 2020**

Subject: **Repair Procedure Revision- Brake Light Switch Adjustment**


SERVICE INFORMATION

YEAR	MODEL
2019-2020	Ryker

Vehicles may indicate brake light switch failure. One of the probable cause is the adjustment of the brake light switch / low pressure switch.

BUDS2 will return one or more of the following codes:

- C0040 - Brake light switch failure
- P061E - Brake signal state Invalid
- P0504 - Brake signal not plausible
- C0042 - Low brake pressure switch
- C1182 - Brake failure (low pressure switch)



PROCEDURE

Refer to the following procedures.

- TASK:*INSPECTING THE ADJUSTMENT OF THE BRAKE LIGHT SWITCH / LOW PRESSURE SWITCH (BLS/LPS).*
- TASK:*ADJUSTING THE BRAKE LIGHT SWITCH / LOW PRESSURE SWITCH (BLS/LPS).*

Always refer to the appropriate [ONLINE REPAIR MANUAL](#) for the latest informations and procedures.
