



# Technical Service Bulletin

## 90 Audi pre sense - restricted function icon is displayed after engine starts

90 20 54 2059891/1 June 29, 2020.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4	2017 - 2022	All	Multifunction camera
Q7	2017 - 2020	All	Multifunction camera
A5, Q5	2017 - 2022	All	Multifunction camera

## Condition

### Customer states:

- The symbol for “Audi pre sense not available at the moment” is shown for about 10 seconds after engine starts and then it disappears.



**Figure 1.** Symbol “Audi pre sense not available at the moment”.

## Technical Background

This icon is shown for about 10 seconds after switching on the ignition, because Audi pre sense is not available at the time. The front camera for driver assist systems R242 needs about 10 seconds to start up.

More information is included in Self-Study Program 970363– 2017 Audi Q7 Occupant Protection and Infotainment System More Info | Launch. This SSP is a prerequisite to the 2017 Q7 ILT and elaunch package.

## Production Solution

Not applicable.



# Technical Service Bulletin

---

## Service

No repair is available at this time.

1. Do not perform any repairs. Any repairs for this concern may be denied.
2. Inform the customer that it takes the front camera for driver assist system (R242) about 10 seconds to start up and the icon informs the driver of this fact. This is normal behavior.

## Warranty

This TSB is informational only and not applicable to any Audi Warranty.

## Additional Information

More information on this system can be found in the following resources:

- SSP: 970363— 2017 Audi Q7 Occupant Protection and Infotainment System More Info | Launch.

All part and service references provided in this TSB (2059891) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.