

Y1A Charging Interrupts with Delta Wallbox Chargers

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Taycan	2020	Y1A	N/A	N/A

Revision History

Revision	Release Date	Changes
0	June 29, 2020	Original document

Condition

During charging sessions on Delta DC Wallbox EV Charger, interruptions may occur at different vehicle state of charge.



Technical Background

Due to a software issue in the Delta DC Wallbox EV Charger, a communication request from the vehicle may not correctly be answered by the charger. This may result in the vehicle ending the charging process prior to reaching the desired state of charge.

Service Information

Delta is aware of this matter and is actively working on a software update to resolve the issue.

If a Taycan experiences an interrupted charging session on a Delta DC Wallbox EV Charger, the charging session may be manually restarted. No repairs should be attempted at this time. Once a resolution is available, this bulletin will be updated.

Search Items

DC Charging; Delta; DC

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.
