

	SERVICE BULLETIN (SB-20-002)	
Arcimoto, Inc.	Date: 06/30/2020	Rev: 0

SUMMARY

Arcimoto Inc. hereby reports a service bulletin that affects quantity one hundred and four (104) Arcimoto FUVs produced between September 19, 2019 and May 15, 2020.

Note: Fields left blank will be marked "NR" meaning "Not Reported" in public view.

Communication ID: SB-20-001	Communication Date: 06/30/2020
<p>Concise Summary: Dual electric motors may experience reduced reliability or life-span, due to allowing fluid ingress without egress. The issue will be addressed with gasketing to prevent fluid ingress, and installation of at least one drain-hole to ensure fluid egress. Based on field reports, the issue of fluid ingress without egress has occurred when the vehicle is stationary and not being operated on a public road/ highway. Therefore, at this time there is no data to suggest a regulatory or safety issue that would require a recall.</p>	

Selected Products:			
Make/Brand Name	Model/Tire line	Model Year/Tire Size	Remove Product
Arcimoto	FUV	2019	Remove
Arcimoto	FUV	2020	Remove

Components (select a maximum of 5):
--

Adaptive Equipment	Exterior Lighting	Parking Brake	Steering
Air Bags	Forward Collision	Power Train	Structure
Back over prevention	Fuel System	Seat Belts	Suspension
Electrical	Fuel System Diesel	Seats	Trailer Hitch
Electronic Stability Control	Fuel System Other	Service Brake	Visibility
Engine And Engine Cooling	Lane Departure	Service Brake Air	Wheels
Equipment	Latch	Speed Control	Unknown

	SERVICE BULLETIN (SB-20-002)	
Arcimoto, Inc.	Date: 06/30/2020	Rev: 0

Select the button below to choose the document you want to upload. The filename should be 150 characters or less. Only a PDF file is allowed. The maximum size is 50 MB.

Check the box below if the submission contains Personally Identifiable Information (PII):

Personally Identifiable Information (PII)

Comments:

Owners will be notified by mail and instructed to contact Arcimoto to schedule a service appointment(s) to have their motors serviced. There will be no charge to vehicle owners for this service. To the best of our knowledge, no owners have incurred any costs resulting from this issue.

	SERVICE BULLETIN (SB-20-002)	
Arcimoto, Inc.	Date: 06/30/2020	Rev: 0

1 REVISION HISTORY

Function	Role	Name	Signature	Date
Author	Dir Q&RA	Pete Z	<insert name>	06/30/2020
Author	RA-RCP	Matt M	<insert name>	06/30/2020
PO	Dir Q&RA	Pete Z	<insert name>	06/30/2020
Approver	Dir Q&RA	Pete Z	<insert name>	06/30/2020

Revision		Reason for change;
#	Date Issued	Summary of change from prior Revision
0	06/30/2020	Initial Issue Internal Outline of MCP submission.