

SSM 48900 - 2020 Explorer - Leather Steering Wheel - Leather Covering Untucked/Separating

Some 2020 Explorer vehicles equipped with a leather wrapped steering wheel may exhibit the leather covering becoming untucked or separating from the steering wheel. The leather may be able to be re-adhered to the steering wheel. Steering wheel replacement may not be necessary. Refer to Workshop Manual (WSM), Section 211-04 Steering Column > General Procedures > Steering Wheel Cover Repair for the updated repair procedure. It is not necessary to remove the steering wheel to perform this procedure.

APPLICABLE VEHICLES
2020 CAR: TW U625N EXPLORER