

CUSTOMER SERVICE

SERVICE ACTIONS -AJ20P ENGINE COOLANT PUMP OPERATION



SERVICE ACTION N451 – OWNER NOTIFIED		SERVICE ACTION H291 – OWNER NOTIFIED	
AFFECTED MODELS WITH 4 CYL AJ20P ENGINE	2019-2020 MY DISCOVERY; DISCOVERY SPORT; RR EVOQUE; RR VELAR; RANGE ROVER; RANGE ROVER SPORT	AFFECTED MODELS WITH 4 CYL AJ20P ENGINE	2019-2020 MY E-PACE; F-TYPE; F-PACE; XE; XF.
VOLUME AFFECTED	56,971 USA	VOLUME AFFECTED	33,404 USA
REPAIR	Affected vehicles require a software update to the Powertrain Control Module (PCM) to prevent radiator fans running continuously	REPAIR	Affected vehicles require a software update to the Powertrain Control Module (PCM) to prevent radiator fans running continuously
REPAIR TIME	0.2 hrs + Drive in/out	REPAIR TIME	0.2 hrs + Drive in/out
CAMPAIGN LAUNCH	June 4th 2020	CAMPAIGN LAUNCH	June 4 th 2020
Notes	Unsold Inventory 9,146	Notes	Unsold Inventory 5,716

Fix on fail Water Pump repair published in TSB JLRTB02030NAS1