

SSM 48956

2018 F-150 - 2.7L EcoBoost - Illuminated MIL With DTC P2196 And/Or P2198

Some 2018 F-150 vehicles equipped with a 2.7L EcoBoost engine may experience an illuminated malfunction indicator lamp (MIL) with diagnostic trouble code (DTC) P2196 and/or P2198 stored in the powertrain control module (PCM) with no drivability concerns. Engineering is working to implement a solution for this condition. In the interim, clear the DTCs with the appropriate Ford scan tool and schedule a follow-up appointment with the customer for mid-August 2020. Advise the customer that a repair is expected to be available in early August 2020 and that the condition has no effect on vehicle operation or long term durability.

Vehicles:

2018 F-150 (P552) (FC)