

SERVICE ACTIONS H291 AND N451 TEMPORARILY SUSPENDED



NAS20.06.006

WORKSHOP

CAN/USA

AFTERSALES BULLETIN

JUNE 10, 2020

TO: all Jaguar Land Rover Authorized Retailers

RE: Service Actions H291 and N451 Temporarily Suspended

Please be advised that effective immediately Service Actions H291 and N451, *Coolant Pump Operation*, have been temporarily suspended. A concern has been identified with the Pathfinder software release that may be missing parts of the software calibration that could result in an unsuccessful software download.

The Technical Bulletins have been suspended in TOPIx. The DDW, TOPIx, and BBSS flags against affected VIN have been turned 'off'.

A further Pathfinder release to correct this is expected on or before July 10, 2020. When this is completed, the bulletins will be re-published and this Aftersales Bulletin updated to confirm when repairs may recommence.

Jaguar Land Rover apologizes for any inconvenience this may cause.

For questions regarding the content of this publication, please contact:

Alan Clarke

Critical Concern Engineer

301-509-1563

aclark43@jaguarlandrover.com

Jaguar Land Rover North America, LLC

100 Jaguar Land Rover Way

Mahwah, NJ 07495