

LATEST VEHICLE CONCERN FIXES

ELECTRICAL



Touchscreen Image Scrolling / Jumping	2020MY Range Rover Evoque
<p>Customer Voice:</p> <ul style="list-style-type: none">Customer states both upper and lower screen images are jumping. <p>Technical Description:</p> <ul style="list-style-type: none">APIX cable lengths may not be compatible with the APIX tuning parameters in the IDMA, ICDM and IMC. <p>Status:</p> <ul style="list-style-type: none">The length of the APIX cables are currently under investigation. Please follow guided diagnostics and submit a TA case for technical assistance with the results of the diagnostics.	 

