## Latest Vehicle Concern Fixes POWERTRAIN





Judder from Vehicle While Turning	16MY onward RR Evoque, Discovery Sport
<ul> <li><u>Customer Voice</u>:</li> <li>There is a noise when turning.</li> <li>There is a judder/vibration when turning.</li> <li><u>Technical Description</u>:</li> <li>The oil is found to be discolored and some debris is identified on the drain plug magnet (this is normal).</li> <li><u>Status:</u></li> <li>Perform the "Active on-demand coupling service procedure" found in the TOPIx workshop manual 205-02B Rear Drive Axle/Differential - Vehicles With: Active Driveline.</li> <li>This routine is also linked in the diagnosis symptom chart recommended action section within the same section of the TOPIx workshop manual.</li> </ul>	