

SERVICE BULLETIN 578: 30 AMP FUSE



Notice Information

Ref	15001
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Sales Executive, Sales Manager, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

TOL NOTICE (US&CA) – June 15, 2020

TOL Ref. # 15001-SVC

SERVICE BULLETIN 578: 30 Amp Fuse

Triumph has released **Service Bulletin 578**. Internal investigations have identified the need to check the 30A fuse and fuse holder (located on the starter motor solenoid) and, if necessary, clean and fill the fuse holder with grease and fit a new fuse as described in the procedure outlined in [Service Bulletin 578](#).

SB 572: 30 Amp Fuse			
Bulletin #	Models Affected	VIN Range	Markets
578	Tiger 900 Tiger 900 GT Tiger 900 GT Pro Tiger 900 Rally Tiger 900 Rally Pro Tiger 900 GT - LRH	From 978905 to AB7717	All

Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next visit to the dealership.

Consult **Triumph Online (TOL) / Service Bulletin Page** (Bulletin # 578) or the attached **Service Bulletin 578** PDF for additional information including Fitting, Warranty Claim and Part Ordering instructions. Please also ensure that all relevant staff are up to date on these service instructions.

Reminder: Use the “**VIN Enquiry**” function within TOL (found under the **Service / Technical** drop down menu) to search for any outstanding bulletins or recalls whenever a new motorcycle arrives or a Triumph owner visits your dealership.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.