

# **Technical Service Bulletin**

#### PSS 90 Instrument cluster: The center display is black

90 20 60 2057082/2 July 15, 2020. Supersedes Technical Service Bulletin Group 90 number 19-34 dated November 26, 2019 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2019	All	Audi virtual cockpit
Q3	2020	000001 - 000731	Audi virtual cockpit

## Condition

REVISION HISTORY				
Revision	Date	Purpose		
2	-	Republishing Revised header (Added MY) Revised <i>Service</i> (Added estimated software release date)		
1	11/26/2019	Initial publication		

#### **Customer states:**

- The central display area in the Audi virtual cockpit is black and does not show the expected tab, no matter which tab is currently selected (Figure 1).
- The tachometer and speedometer remain visible and operational.



Figure 1. Central display area is blank.

#### Workshop findings:

• No relevant DTCs are entered in the vehicle.

© 2020 Audi of America, Inc.

Page 1 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



## **Technical Service Bulletin**

### **Technical Background**

A software malfunction can cause the center display to blank out.

## **Production Solution**

Not applicable.

### Service

- 1. Explain to the customer that a solution is forthcoming for the 3rd quarter of 2021 and that no repairs are necessary at this point Do not replace any components for this condition since this will not resolve the customer's concern.
- 2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*), or through the Technical Assistance page in Elsa.

#### Warranty

This TSB is informational only and not applicable to any Audi Warranty.

### **Additional Information**

All part and service references provided in this TSB (2057082) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

© 2020 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.