

GPOP - Issue Review System

Part Number: 04672794A\$

Part Description: Sensor - Blind Spot Detection (Module)

Issue Before replacing this sensor, check RRT# 20-035, if applicable.

Description: Before replacing part, run an alignment reset for LBSS in WiTech.

Contact *FCA Redacted Content* if above procedures do not correct the issue.

If no response in 15 minutes, proceed with repair.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
