

STAR ONLINE PUBLICATION


Case Number: S2008000080

Release Date: 06/02/2020

Symptom/Vehicle Issue: Intermittent Crank Not Start

Customer Complaint/ Technician Observation: Owner complains at times that the vehicle will crank and not start. Technician observed the vehicle was setting P0103 - Mass or Volume Air Flow 'A' Circuit High set as stored or active.

Repair procedure: Inspect, test and replace the involved main relay as needed.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found