



SIB 61 15 20

2020-06-05

DELIVERY STOP: TRUNK LOCK SWITCH WIRING HARNESS

MODEL

E-Series	Model Description	Production Date
G20	3 Series Sedan	March 25, 2020 – March 26, 2020

AFFECTED VEHICLES

Vehicles which require this Campaign to be completed will show it as “Open” when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System), ISPA Next or Warranty Vehicle Inquiry.

SITUATION

BMW AG has issued a Delivery Stop (effective June 5, 2020) on a small number of Model Year 2020 BMW 3 Series vehicles that were produced on March 25, 2020 and March 26,2020. The wiring harness from the Body Domain Controller (BDC) to the hotel setting switch is missing.

Do not deliver to a customer, a New, Certified Pre-Owned or Used vehicle subject to a Delivery Stop, until the vehicle is repaired. Do not use or sell replacement equipment/parts subject to a Delivery Stop.

The bulletin will be updated when additional information becomes available.