
## ATTENTION:

GENERAL MANAGER PARTS MANAGER CLAIMS PERSONNEL SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.



© 2019 Subaru of America. Inc. All rights reserved.

SUBARU.

QUALITY DRIVEN® SERVICE

NUMBER: 15-238-19R

**DATE:** 03/11/19

**REVISED:** 07/21/20

## SERVICE INFORMATION BULLETIN

**APPLICABILITY:** 2018-19MY Legacy and Outback

2017-19MY Impreza 2018-19MY Crosstrek 2019MY Forester

2019MY WRX 2019MY Ascent 2018-19MY BRZ

**SUBJECT:** Enhanced CD Incompatibility with Harman

Gen 3.0 and 3.1 Head Units

**IMPORTANT:** This Service Information Bulletin has been removed following Software Version 6 release to the field. Please refer to TSB **15-211-17R** for Gen 3.0 and TSB **15-236-18R** for Gen 3.1 the update on this condition.

## CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

## Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.