On-car analysis list from July 24th, 2020 please contact VW Helpline before attempting repair

| | Models | MY | Engine | Transmission | Topic | Customer Complaint |
|------------|---|-------|----------------------------|--------------|--------------------|---|
| Powertrain | | | 1.4T | | · | Customer states MIL-on |
| | Jetta | 19-20 | (DGXA / DJXA) | All | MIL-on P0496 | (Must have P0496 in the ECM) |
| | Jetta | 19-20 | 1.4T (DGXA / DJXA) | All | MIL-on U0284 | Customer states MIL-on |
| | | | | | | (Must have U0284 in the ECM) |
| | | | (= =:::, =::::, | | | (untouched vehicles) |
| | Atlas, Atlas Cross | 19-21 | 3.6L | All | Engine Oil Leak | Customer states engine oil leak (leaking from cylinder head valve cover ONLY) |
| | Sport | 15-21 | (CDVC) | All | Eligilie Oli Leak | (untouched vehicles) |
| | | | 4.47 | | | Customer states engine oil leak |
| | Jetta, Golf, | 19-20 | 1.4T | All | Engine Oil Leak | (UPPER or LOWER ENGINE OIL PAN ONLY) |
| | SportWagen | | (DGXA / DJXA) | | | (untouched vehicles) |
| | Jetta | 18-19 | 1.4T (CZTA, DGXA, DJXA) | All | MIL-on P0111 | Customer states MIL-on |
| | | | | | | (Must have P0111 in the ECM) |
| | | | 2.0T | | | (untouched vehicles) Customer states MIL-on |
| | Tiguan | 20 | (DGUA) | All | MIL-on P0442 | (Must have P0442 in the ECM) |
| | | | · | | | Customer states MIL-on |
| | Atlas, Atlas Cross | 18-21 | 3.6L | All | MIL-on P2407 | (Must have P2407 in the ECM) |
| | Sport | | (CDVC) | | | (For MY18 & MY19, software must be level 9970 or higher) |
| | Tiguan | 20 | 2.0T (DGUA) | All | MIL-on P11** | Customer states MIL-on (Must have P11A1/P11A2/P11A3/P11A4/P11A5/P11A6/P11A7/P11A8/ P11A9/P11AA/P11AB/P11AC/P11AD/P11AF/P11AF/P11B0 in the ECM) (Untouched vehicles) |
| | Jetta GLI, Golf GTI, | 19 | 2.0T | All | HPFP Bolt | Customer states MIL-on, HPFP mounting bolts loose/broken |
| _ | Tiguan | | (DKFA, DGUA) | | | (HPFP bolts must be loose/broken) |
| Electrical | Passat | 19-20 | All | All | No Terminal 15 | Customer states "No Crank/No Start" (untouched vehicles) |
| Body | Jetta | 19 | All | All | Headlights cracked | Customer states both headlights are cracked (untouched vehicles) |
| | | | | | | (CANNOT have outside influence) Customer states noise heard when adjusting air distribution on HVAC |
| | Atlas | 19-20 | All | All | Dash Noise | controls |
| | 710103 | 13 20 | , | 7.111 | Bush Noise | (untouched vehicles) |
| | | | | | | Wind Noise from the Front Driver or Passenger Door |
| | Atlas | 19-20 | All | All | Wind Nosie | (untouched vehicles) |
| | | | | | | (CANNOT have outside influence) |
| Other | Jetta, Jetta Wagon, Jetta SportWagen, Golf, Golf Wagon, Beetle, Beetle Convertible | 09-14 | 2.0 TDI (CJAA/CBEA) | All | TB Data P0401 | Customer states MIL-on (Must have P0401 in the ECM) (Must be performing TB 01-18-13 / 2034898) (concern group TDI Emissions) (Fill out attachment in VTA: Gen I-TDI Survey) |