On-car analysis list from July 28th, 2020 please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Jetta	19-20	1.4T	All	MIL-on P0496	Customer states MIL-on
			(DGXA / DJXA)			(Must have P0496 in the ECM) Customer states MIL-on
	Jetta	19-20	1.4T	All	MIL-on U0284	(Must have U0284 in the ECM)
			(DGXA / DJXA)			(untouched vehicles)
	Atlas, Atlas Cross	10.21	3.6L	A.II	Faring Oil Look	Customer states engine oil leak
	Sport	19-21	(CDVC)	All	Engine Oil Leak	(leaking from cylinder head valve cover ONLY) (untouched vehicles)
						Customer states engine oil leak
	Jetta, Golf, SportWagen	19-20	1.4T (DGXA / DJXA)	All	Engine Oil Leak	(UPPER or LOWER ENGINE OIL PAN ONLY)
	Sportwagen		(DGAA / DJAA)			(untouched vehicles)
	Jetta	18-19	1.4T (CZTA, DGXA, DJXA)	All	MIL-on P0111	Customer states MIL-on
						(Must have P0111 in the ECM) (untouched vehicles)
			2.0T			Customer states MIL-on
	Tiguan	20	(DGUA)	All	MIL-on P0442	(Must have P0442 in the ECM)
	Atlas, Atlas Cross Sport	18-21	3.6L (CDVC)	All	MIL-on P2407	Customer states MIL-on
						(Must have P2407 in the ECM)
						(For MY18 & MY19, software must be level 9970 or higher)
						Customer states MIL-on
	Tiguan	20	2.0T	All	MIL-on P11**	(Must have P11A1/P11A2/P11A3/P11A4/P11A5/P11A6/P11A7/P11A8/
	Hguan	20	(DGUA)	All	WILL OHT II	P11A9/P11AA/P11AB/P11AC/P11AD/P11AE/P11AF/P11B0 in the ECM)
						(Untouched vehicles)
	Jetta GLI, Golf GTI,	19	2.0T	All	HPFP Bolt	Customer states MIL-on, HPFP mounting bolts loose/broken
	Tiguan	19	(DKFA, DGUA)	All	HPFP BOIL	(HPFP bolts must be loose/broken)
Electrical						
	Passat	19-20	All	All	No Terminal 15	Customer states "No Crank/No Start"
						(untouched vehicles)
	Dassat	16-20	All	All	Seat Heater	Driver seat heater inoperative
	Passat	10-20	All	All	Seat neater	(Must have fault code B139813 in A/C/heating electronics) (untouched vehicles)
						Customer states both headlights are cracked
	Jetta	19	All	All	Headlights cracked	(untouched vehicles)
						(CANNOT have outside influence)
Body	Atlas	19-20	All	All	Dash Noise	Customer states noise heard when adjusting air distribution on HVAC controls
	Atlas	13-20	All	All	Dasii Noise	(untouched vehicles)
						Wind Noise from the Front Driver or Passenger Door
	Atlas	19-20	All	All	Wind Nosie	(untouched vehicles)
						(CANNOT have outside influence)
Other	Jetta, Jetta					Customer states MIL-on
	Wagon, Jetta		2.0 = 2:			(Must have P0401 in the ECM)
	SportWagen, Golf,	09-14	2.0 TDI	All	TB Data P0401	(Must be performing TB 01-18-13 / 2034898)
	Golf Wagon, Beetle, Beetle		(CJAA/CBEA)			(concern group TDI Emissions)
	Convertible					(Fill out attachment in VTA: Gen I-TDI Survey)
	CO CI CIDIC					