

SSM 49038 - 2020 F-Super Duty – High Mounted Stoplamp Camera - Various Concerns - Built Through 26-May-2020

Some 2020 F-Super Duty vehicles built on or before 26-May-2020 equipped with a high mounted stoplamp camera, may exhibit various concerns such as poor image quality, flickering and/or intermittent blank screen. If a vehicle exhibits any of these conditions replace the high mounted stoplamp camera. Refer to Workshop Manual (WSM), Section 417-01. For claiming, use causal part 19G490 and applicable labor operations in Section 11 of the Service Labor Time Standards (SLTS) Manual.

APPLICABLE VEHICLES
2020 TRUCK: FE P558N SUPER DUTY