

# WKG4 Workshop Campaign - Replacing PCCB brake disc covers and air guides

Version 2

---

## Update 7/17/20

Please be advised that the WKG4 TI has been revised to include caliper bolts (4 qty) that must be replaced according to the workshop manual instructions.

---

## Overview

There is a possibility that the braking performance of the PCCB brake system on the affected vehicles may not meet the driver's expectations when the brake discs on the rear axle are wet. This can happen, for example, when driving for long periods of time in heavy rain.

In this case, the customer will have to apply greater brake pressure for a short time in order to achieve the usual braking response.

The cover plates and brake air guides on the brake system on the rear axle must therefore be replaced by optimized versions to improve wet braking behavior.

Please arrange for this measure to be carried out on the affected vehicles the next time the vehicles come into the workshop.

Model type	911 (992)
Model year	2020
Vehicle specifications	Porsche Ceramic Composite Brake PCCB (1-no. 1LQ)
Number	24

### Porsche Mobility

If requested, the mobility of the affected customer can be guaranteed by offering a suitable replacement vehicle.

Please invoice this additional service with the campaign scope via WWS.

### Parts required

Part No.	Designation	Quantity/vehicle	Parts return*
992615611F	Left cover plate	1 ea.	No
992615612F	Right cover plate	1 ea.	No
9P1615457H	Left spoiler	1 ea.	No
9P1615458H	Right spoiler	1 ea.	No
N 10456004	Head screw 6x12	4 ea.	No

---

\* The parts must be stored until such a time as the related warranty or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the genuine remanufactured parts process or be scrapped.

**Ordering required parts:** Parts should be ordered as needed, with no need for PRMS ticket or email for release.

### Warranty processing

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

#### Scope 1:

Damage code	WKG4 66 000
Repair code	2
Working time	172 TU

### Further information

Work instruction	TI No. 167/19, Group 4, Service, WKG4
Vehicle list and allocation	See PCSS or attached VIN list for reference
Technical Information	See PCSS or attached TI for reference

---

[992 4 167-19 WKG4 - Replace PCCB brake disc covers and air guides \(Workshop campaign\)\\_rev1.pdf](#)

**718.2 KB**

(39 views)

[WKG4 VIN List.xlsx](#)

**8.6 KB**

(152 views)

Created by [Ryan Cooney](#) on Jul 8, 2020 3:57 PM. Last modified by [Ryan Cooney](#) on Jul 17, 2020 7:05 PM.

Categories: Workshop Campaigns, 911 Carrera

Tags : [911](#), [pccb](#), [992](#), [wkg4](#)

1198 Views

[Report Abuse](#)

Content and Topics

Personal

Manage

Create

Your Groups >

Edit Profile >

Admin Console >

Discussion >

Your Content >

Change Password >

PPN Administration>

Files >

Your Places >

Document >

Collaboration >

Document

Blog Post >

Poll >

Event >

Photo Album >

Idea >

Space >

Group >

© 2020 Dr. Ing. h.c. F. Porsche AG. [Legal notice.](#) [Copyright.](#) [Terms of use.](#) [Privacy Policy.](#) [Cookie Policy.](#) [009](#)