

WLG8 Stop Delivery – Re-bonding rear window

Version 2

Update 7/24

Workshop instructions for carrying out WLG8 are now available and have been posted to this page. Repairs may begin immediately.

Stop Delivery

The affected vehicle must not be delivered until the required remedial measure has been carried out.

Overview

There is a possibility that the rear window is not bonded sufficiently to the body on the affected vehicle. As a result, there is no guarantee that the degree of correct bonding will be sufficient to meet the required properties.

To avoid this, the rear window must be re-bonded.

Model type	Taycan 4S (Y1A)
Model year	2020
Number of affected vehicles	1

Vehicle usage

The affected vehicle may only be driven for loading and unloading purposes in the transport chain.

Further use is not permitted. Test drives are to be omitted.

Test instruction and remedial measure

Will be communicated once available (approx. end of cw 31).

[WLG8_RemedY_Y1A_EN.pdf](#)

705.2 KB

(35 views)

[WLG8 Stop Delivery VIN List.xlsx](#)

8.1 KB

(245 views)

Created by [Ryan Cooney](#) on Jul 16, 2020 10:02 PM. Last modified by [Ryan Cooney](#) on Jul 24, 2020 5:50 PM.

Categories: Taycan, Workshop Campaigns, Stop Sale

Tags : [stop delivery](#), [taycan](#), [my I](#), [wlg8](#)

1103 Views

[Report Abuse](#)

Content and Topics

Personal

Manage

Create

- Your Groups >
- Your Content >
- Your Places >
- Edit Profile >
- Change Password >
- Admin Console >
- PPN Administration>
- Discussion >
- Files >
- Document >
- Collaboration >
- Document
- Blog Post >
- Poll >
- Event >
- Photo Album >
- Idea >
- Space >
- Group >

© 2020 Dr. Ing. h.c. F. Porsche AG. [Legal notice.](#) [Copyright.](#) [Terms of use.](#) [Privacy Policy.](#) [Cookie Policy.](#) **009**