

# WLE3 Workshop campaign - Replacing 12V vehicle electrical system battery

Version 1

## Overview

Due to a manufacturing error, there is a possibility that the internal current sensor for the 12-volt vehicle electrical system battery does not meet the required specifications on the affected vehicles. As a result, the charge state will be calculated incorrectly and the 12-volt vehicle electrical system battery will then be completely discharged when the vehicle is parked up for extended periods without an external power supply.

To prevent this from happening, the 12-volt vehicle electrical system battery (lithium-ion battery) must be replaced.

Please arrange for this measure to be carried out on the affected vehicles during the next workshop visit or before handing the vehicles over to customers.

Model type	Taycan (Y1A)
Model year	2020
Number	578

Part No.	Designation	Quantity/vehicle	Parts return*
V04015001BA	12-volt vehicle electrical system battery	1 ea.	No
PAF106825	Cheese head bolt, M8 x 50 – Strut to body	4 ea.	No

\* The parts must be stored until such a time as the related warranty or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the genuine remanufactured parts process or be scrapped.

## Parts Availability and Ordering

Parts stock is currently at 40%. Please only order parts as required for vehicles in the workshop requiring the repair, or appointments made.

As parts are limited, please do not order additional parts, outside of what is required.

## Warranty processing

Validity:

This workshop campaign will be carried out up to 6/26/2025 and will be closed by the specified date.

Please note that warranty claims can only be processed before this date.

Scope 1:

Damage code	WLE3 66 000 2
Working time	163 TU

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

## Porsche Mobility

If requested, the mobility of the affected customer can be assured by offering a suitable replacement vehicle. Please invoice this additional service with the campaign scope via WWS.

## Further information

Work instruction	TI No. 66/20, Group 2, Service, WLE3
Vehicle list and allocation	See PCSS or attached VIN list for reference
Technical Information	See PCSS or attached TI for reference

[WLE3 VIN List.xlsx](#)

**19.9 KB**

(93 views)

[Y1A 2 66-20 WLE3 Replacing Vehicle Electrical System Battery \(Workshop Campaign\).pdf](#)

**84.0 KB**

(57 views)

Created by [Ryan Cooney](#) on Jul 29, 2020 2:49 PM. Last modified by [Ryan Cooney](#) on Jul 29, 2020 3:04 PM.

Categories: Taycan, Workshop Campaigns

Tags : [battery](#), [12v](#), [taycan](#), [wle3](#)

625 Views [Report Abuse](#)

Content and Topics	Personal	Manage	Create
Your Groups >	Edit Profile >	Admin Console >	Discussion >
Your Content >	Change Password >	PPN Administration>	Files >
Your Places >			Document >
			Collaboration >
			Document
			Blog Post >
			Poll >
			Event >
			Photo Album >
			Idea >
			Space >
			Group >

© 2020 Dr. Ing. h.c. F. Porsche AG. [Legal notice](#). [Copyright](#). [Terms of use](#). [Privacy Policy](#). [Cookie Policy](#). [009](#)