

FT4606R1 Various Sika Seams are Cracking (40')		
Technical writer name / nom rédacteur technique	Manual/manuel, section	1

André Pelletier

Parts/ pièces, description	Part Number / Numero de pièce	QTY / Qté
PANEL MOLDING NO PAINT	N81513-06	6
TRIM ROOF- SIDE	N93975-1	3
TRIM ROOF- SIDE	N93975-2	3
ADHESIVE LOCTITE H8000	N66004	125ml
* order everything on the first order. For N66004 order 7 tubes.		

Labour level 1 / main d'oeuvre niveau 1	18.1 h (done by third party CAB Fleet)
---	--

MQR	7621-778
-----	----------

Client	Order/Lot	Road numbers / No de véhicule		VIN / NIV		QTY / QTÉ	Lang.	Customer Group/ Groupe client	Target market / marché cible	Plant / Usine	Model / modèle	NR	R1
Austin - CMTA - Texas	L704	5051	5068	L82J7E4500471	L82J2E4500488	18	E	-	US	PLB	40	x	x
Austin - CMTA - Texas	LA18	5151	5158	L82J0H9775770	L82J3H9775777	8	E	-	US	PLB	40	x	x