



TO: all Jaguar Land Rover Authorized Retailers
RE: Service Actions H291 and N451 Reinstated

NOTE: [this bulletin updates/supersedes Aftersales Bulletin NAS20.06.006.](#)

Please be advised that effective immediately Service Actions H291 and N451, *Coolant Pump Operation*, have been reinstated. The concern referenced in Aftersales Bulletin NAS20.06.006 with the Pathfinder software release has been rectified.

Updated Technical Bulletins have been published to TOPIx. All Jaguar E-PACE (X540) and 2019 model year Land Rover Range Rover Evoque (LV) vehicles have been temporarily removed from these programs and will be the subject of a future update.

The DDW, TOPIx, and BBSS flags against affected VIN have been turned 'on.

Jaguar Land Rover apologizes for any inconvenience this may cause.

For questions regarding the content of this publication, please contact:

Alan Clarke Critical Concern Engineer
301-509-1563 aclark43@jaguarlandrover.com

Jaguar Land Rover North America, LLC
100 Jaguar Land Rover Way
Mahwah, NJ 07495