



## Boom! Related P&A Kit Bulletins

- PAB1001: Boom! Box Audio System - Out of Warranty Repair Process
- PAB1006: Boom! Amplifier Software Update
- PAB1012: Boom! Audio Bike-to-Bike Communications (CB) Kit Additional Requirements

## New Software Update

### Update 1.22.0.3: Boom! Box 4.3/6.5GT/6.5 CVO GT

- Navigation Prompt setting was not saved during ignition cycle. Navigation Prompt setting On/Off will now persist through key cycle and ignition.
- Customer was not able to save addresses to the radio. Customer is now able to save addresses.

## Previous Software Updates

### Update 1.22.0.2: Boom! Box 4.3/6.5GT/6.5 CVO GT

- Enable new Parts and Accessories (P&A) headset compatibility.

### Update 1.22.0.1: Boom! Box 4.3/6.5GT/6.5 CVO GT (Release date 12-05-2017)

#### Fixes

- Arrival time showed the current time after user deviated from a route.
- Next turn area displayed an arrow with the current street name.
- Special Alpha Jump characters were not displayed.
- The Short Message Service (SMS) repeat button wouldn't read the message clearly if pressed multiple times before it has completed the readout.
- Audio paused after loading a ringtone.
- Voice Recognition (VR) not working after an ignition cycle.
- Local media preset inconsistent between shutdowns.
- User was unable to search for preferred Point Of Interest (POI) after simulation sleep.
- Constant "Game Start" pop-ups.
- Presets from Universal Serial Bus (USB) drive 1 were still visible on USB drive 2 but not highlighted as available.
- Albums and artists heading were mismatched with list.
- Amplitude Modulation (AM) radio presets not highlighted when USB was unplugged.
- Repeat button NOT enabled on first selection.
- Pre-cal reset did not delete trails.
- Accept screen appeared for less than 15 s after exiting User Off mode.
- Saving or editing emergency number did not work.
- No Siri® pop-up displayed while saving an emergency number.
- Text was missing in the maneuvers list after switching to high contrast mode and then back.
- No initial Siri pop-up initiated.
- Cancel noise was heard when going from VR to Siri.

- Prompt Volume was not updated after changes in Feedback Settings.
- Global Positioning System (GPS) entry changed W(O) to E in Spanish.
- Wireless Headset Interface Module (WHIM) – Low battery pop-up was not shown for passenger headset.
- WHIM – Paired Bluetooth® device name appeared as "Headset".
- Repeat prompt was not working.
- SiriusXM® weather map did not maintain the default zoom level.
- User off mode enabled navigation prompts.
- VR conflict if Siri was launched from phone at the same time with the radio.
- Saved USB presets for drive 2 were replaced by drive 1 after an ignition cycle.
- USB saved as favorite was not highlighted after an ignition cycle.
- Distance to next action bar disappeared before route recalculation instead of being grayed out.
- "Navigation is not ready" displayed when initiating navigation command to "Find Next Gas Station" via VR.
- Fixed temporal displacement control for flux capacitor.
- Various bug fixes.