


Latest Vehicle Concern Fixes

POWERTRAIN



Check Engine Lamp on with a Lack of Power	16MY onward Range Rover, RR Sport, Discovery equipped with TDV6 Engine
<p>Customer Voice:</p> <ul style="list-style-type: none">The Check Engine Lamp is on and there is a lack of power. <p>Technical Description:</p> <ul style="list-style-type: none">P0087-21,22,84 is stored in the PCM for fuel rail/ system pressure too low. <p>Status:</p> <ul style="list-style-type: none">Visually check for obvious signs of a leak near the filter.If a leak is identified, please stop working on the vehicle and raise a TA with a clear & detailed description of the customer symptoms. An engineer may be interested in visiting the vehicle directly to gather additional data. It is important that the system remain undisturbed for analysis.	 A yellow line drawing of a fuel rail system, showing a main rail with several smaller branches, all set against a dark grey rounded square background.

