

Latest Vehicle Concern Fixes

POWERTRAIN



3.0P Supercharger FEAD idler and Supercharger tensioner noise

17MY Onward Range Rover, RR Sport, RR Velar, Discovery, F-TYPE, F-PACE, XE, XF, XJ equipped with AJ126

Customer Voice:

- There is a noise from the engine.

Technical Description:

- The root cause of the noise is the idler pulley and/or tensioner on the Supercharger FEAD Belt.

Status:

- Reference SSMS 74810 and 74811.
- Raise an EPQR and include the following:
 - Video or sound file of the noise.
 - Photographs that detail any evidence of contamination of the pulley and the origin of the contamination.
 - Service history from the vehicle.

