

Latest Vehicle Concern Fixes

POWERTRAIN



AJ20P Misfire

18MY Onward F-PACE, XE, RR
Velar equipped with AJ20P4

Customer Voice:

- The Check Engine MIL is on.
- The engine is shaking.

Technical Description:

- Misfire DTCs are stored in the PCM.

Status:

- Complete primary and secondary diagnosis for the misfire
 - Inspect for and repair any intake or exhaust air leaks
 - Inspection of the electrical circuit and coil
 - Inspection of the electrical circuit and injector
 - Confirm mechanical integrity of the cylinder, valves, etc.
 - Check fuel for contamination
- Raise an EPQR and include results of the diagnosis performed and pictures of the 4 spark plug electrode ends with the cylinders numbered.

